



Equipment And Power Tool Inspection List

Vehicle Issued To: Anthony Rico


Truck # 4

Location: Midland, TX

Description	Serial Numbers				Calibration Frequency
Straight Grinder	PK-401	PK-402	PK-403		N/A
Black light	PK-408				N/A
Large side grinder					N/A
4" Side grinder	PK-404				N/A
Box Drill	PK-405				N/A
DS-1	I-1245				N/A
Coil	CES-105455				N/A
Yoke	PK-407				N/A
Gauss Meter	PK-8235-1				6 Months
UV & White Light Meter	UV Light	#PK-210701029	White Light	# PK-1839001588	6 Months
Dual Light Meter					6 Months
Profile Gauges	PK-10723-2	PK-22122-1	PK-22122-2 PK-12-2722-3	PK-22122-3 PK-10723-1	3 Years
Test Bar	PK-25437				3 Years
Pit Gauge	PK-JZ23JG0051				1 Year
UTT Unit	PK-20050				1 Year
UT Unit					1 Year
ET Unit					1 Year
Step Block	PK-E10225				1 Year
Depth Gauge	PK-2306211150				6 Months
Digital Caliper	PK-1608211172				6 Months
Dye Block Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Castrol Strip Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Temp Gun Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Flashlight Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Centrifuge Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	N/A

Completed By: 

Date: 1/26/23

Approved By: 

Date: 1/30/23

NOTE: please remove all unsafe tools from usage and report to supervisor.